

Safe Work Practice (SWP)

Name of Task: Solderin

Department/Unit: Trades

Personal Protective Equipment or other required equipment or other safety considerations:

- Eye Protection Required
- Long or loose hair must be tied back or contained
- No loose-fitting clothing
- No jewelry, watches, rings, necklaces etc.
- Hearing Protective Required
- CSA Approved Safety Footwear required
- Appropriate Gloves Required

Hazards:

- Burns
- Fumes
- Cuts and Lacerations
- Chemical Burns and Irritations

Require				
Training		Safety Practices)		
		Shop safety orientation Read and understand SWP		
		For students, practical demonstration and Instructor supervision required		
Pre-Operational Safety Checks		 Inspect required personal protective equipment and replace if required. Ensure no slip/trip hazards are present in workspaces. Faulty equipment must not be used. Immediately report suspect equipment. Locate and ensure you are familiar with the operation of the torch. Ensure work area is free of flammable hazards. 		
Prohibited		Do not leave this equipment unattended while running		
Activities		Do not touch soldering materials until it has cooled to room temperature		
		Do not touch joints that have been soldered until cooled		
		Do not aim the torch in any direction other than the area of work		
Steps to be taken to complete task safely:				
1	Wear appropriate personal protective equipment (PPE).			
2	Clean area to be soldered, apply flux (if applicable) assemble fittings and pipe.			
3	Start torch			
4	Heat copper and fittings			
5	Apply solder or brazing material.			
6	Draw filler material into joint soon as filler material melts.			
7	Shut off torch			
8	Let cool to room temperature.			
9	After the assembly has cooled, wipe with a damp cloth to remove excess flux			
10	Ensure work area is clean and equipment stored			

If an emergency occurs while conducting this task, or there is an equipment malfunction, shut the equipment off immediately and follow the lock out procedure.

REPORT ANY HAZARDOUS SITUATION TO YOUR INSTRUCTOR/SUPERVISOR IMMEDIATELY

Housekeeping

- Ensure equipment is off.
- Place all materials in their proper storage areas.
- Ensure the equipment is safe, clean and tidy before you leave it.

Responsibilities, Completion and Review

Management and workers to ensure all duties performed in accordance to training, established health and safety regulations/guidelines, policies and procedures (e.g. utilizing personal, protective equipment as per SAFE Work Procedures). Notify Manager or designates (i.e. supervisors) of all occurrences, injuries illnesses or safety and health concerns which are likely to harm themselves, co-workers, or any others who enter the premises.

Completed by and Date: Ashley Ritchie, 1/28/2021	Approved by:
Last Reviewed / Revised by and Date:	Note: This task will be monitored periodically to ensure compliance and effectiveness.